

DOORMART USA's HINGE LOCATIONS

All Measurements to Be Measured From Top to Bottom
(from top of frame or door to top of each hinge)

6-0		6-8		7-0		7-10		8-0	
<i>FRAME</i>	<i>DOOR</i>	<i>FRAME</i>	<i>DOOR</i>	<i>FRAME</i>	<i>DOOR</i>	<i>FRAME</i>	<i>DOOR</i>	<i>FRAME</i>	<i>DOOR</i>
7" 1/2	7" 3/8	5"	4" 7/8	5"	4" 7/8	5"	4" 7/8	5"	4" 7/8
33" 7/16	33" 5/16	35" 1/4	35" 1/8	37" 1/4	37" 1/8	29" 13/16	29" 11/16	30" 1/2	30" 3/8
59" 3/8	59" 1/4	65" 1/2	65" 3/8	69" 1/2	69" 3/8	54" 5/8	54" 1/2	56"	55" 7/8
						79" 7/16	79" 5/16	81" 1/2	81" 3/8
Strike To Be Measured From Top Of Frame To C/L of Strike									
35" 1/16		42"		46"		56"		58"	